Inspection report on compliance with HTA licensing standards Inspection date: **5 November 2024**



Tameside General Hospital

HTA licensing number 12067

Licensed under the Human Tissue Act 2004

Licensed activities

The table below shows the activities this establishment is licensed for and the activities currently undertaken at the establishment.

Area	Making of a post- mortem examination	Removal from the body of a deceased person (otherwise than in the course of an anatomical examination or post-mortem examination) of relevant material of which the body consists or which it contains, for use for a scheduled purpose other than transplantation	Storage of the body of a deceased person or relevant material which has come from a human body for use for a scheduled purpose
Hub site Tameside General Hospital	Licensed	Licensed	Licensed
Mortuary	Carried out	Carried out	Carried out

Summary of inspection findings

The HTA found the Designated Individual (DI) and the Licence Holder (LH) to be suitable in accordance with the requirements of the legislation.

Although the HTA found that Tameside General Hospital ('the establishment') had met the majority of the HTA's standards, two major and one minor shortfall were found against standards for Governance and quality systems and Premises, facilities and equipment.

The HTA has assessed the establishment as suitable to be licensed for the activities specified, subject to corrective and preventative actions being implemented to meet the shortfalls identified during the inspection.

Compliance with HTA standards

Major shortfalls

Standard	Inspection findings	Level of shortfall
GQ6 Risk assessments of the establish	shment's practices and processes are completed regularly, recorded an	d monitored
c) Significant risks, for example to the establishment's ability to deliver postmortem services, are incorporated into the Trust's organisational risk register	Whilst the risk related to lack of roofing over the external body store is on the risk register the works continue to be outstanding after a number of years. Failure to complete these works presents a risk to the security of external body store units and compromises the dignity of the deceased.	Major
PFE1 The premises are secure and w tissue.	ell maintained and safeguard the dignity of the deceased and the integri	ty of human
d) The premises are secure (for example there is controlled access to the body storage area(s) and PM room and the use of CCTV to monitor access)	The door between the public area and the restricted corridor leading into the body store has a missing locking mechanism which prevents the door from being secured.	Major (cumulative)

e) Security arrangements protect against unauthorized access and ensure oversight of visitors and contractors who have a legitimate right of access Whilst cameras are in place throughout the building the Funeral Directors entrance lobby is not covered by CCTV. This lobby area contains body storage units. The lack of cameras does not afford effective oversight of persons entering the mortuary or access to these fridges.

Minor Shortfalls

Standard	Inspection findings	Level of shortfall			
GQ1 All aspects of the establishment's work are governed by documented policies and procedures					
a) Documented policies and SOPs cover all mortuary/laboratory procedures relevant to the licensed activity, take account of relevant Health and Safety legislation and guidance and, where applicable, reflect guidance from RCPath.	The SOP for security audits does not contain sufficient detail of the frequency or method employed.	Minor			

The HTA requires the DI to submit a completed corrective and preventative action (CAPA) plan setting out how the shortfalls will be addressed, within 14 days of receipt of the final report (refer to Appendix 2 for recommended timeframes within which to complete actions). The HTA will then inform the establishment of the evidence required to demonstrate that the actions agreed in the plan have been completed.

Advice

The HTA advises the DI to consider the following to further improve practice:

Number	Standard	Advice
1.	PFE1(d)	The DI is advised to consider replacing the door release button into the body store with a swipe card reader to provide auditable access into the body store area.

Background

Tameside General Hospital has been licensed by the HTA since May 2007. This was the fifth inspection of the establishment; the most recent previous inspection took place in May 2024.

Since the previous inspection, there have been no significant changes to the licence arrangements or the activities carried out under the licence.

Description of inspection activities undertaken

The HTA's regulatory requirements are set out in Appendix 1. The inspection team covered the following areas during the inspection:

Standards assessed against during inspection

A decision to undertake an announced visit was made following a sector wide direction to all establishments to submit an Evidential Compliance Assessments (ECAs) relating to security and access arrangements. The information provided by the establishment raised concerns relating to security measures and processes. Accordingly, this inspection focused on the following standards: GQ1(a), GQ6(a), GQ6(c), PFE1(d) and PFE1(e).

Review of governance documentation

The inspection team reviewed the establishment's ECA document provided by the DI ahead of inspection. Standard operating procedures, risk assessments and policies were reviewed. Audits relating to security and access were inspected as part of the review process.

Visual inspection

The inspection of the facility included a visual assessment of the Mortuary, viewing facilities and external body store.

Audit of records

No audits were conducted during the inspection process.

Meetings with establishment staff

No interviews were conducted during the inspection process.

Report sent to DI for factual accuracy: 11 November 2024

Report returned from DI: No factual accuracy or request for redaction comments were made by the DI

Final report issued: 6 December 2024

Appendix 1: The HTA's regulatory requirements

Prior to the grant of a licence, the HTA must assure itself that the DI is a suitable person to supervise the activity authorised by the licence and that the premises are suitable for the activity.

The statutory duties of the DI are set down in Section 18 of the Human Tissue Act 2004. They are to secure that:

- the other persons to whom the licence applies are suitable persons to participate in the carrying-on of the licensed activity;
- suitable practices are used in the course of carrying on that activity; and
- the conditions of the licence are complied with.

Its programme of inspections to assess compliance with HTA licensing standards is one of the assurance mechanisms used by the HTA.

The HTA developed its licensing standards with input from its stakeholders. They are designed to ensure the safe and ethical use of human tissue and the dignified and respectful treatment of the deceased. They are grouped under four headings:

- consent
- governance and quality systems
- traceability
- premises facilities and equipment.

This is an exception-based report: only those standards that have been assessed as not met are included. Where the HTA determines that there has been a shortfall against a standard, the level of the shortfall is classified as 'Critical', 'Major' or 'Minor' (see Appendix 2: Classification of the level of shortfall). Where HTA standards are fully met, but the HTA has identified an area of practice that could be further improved, advice is provided.

HTA inspection reports are published on the HTA's website.

Appendix 2: Classification of the level of shortfall

Where the HTA determines that a licensing standard is not met, the improvements required will be stated and the level of the shortfall will be classified as 'Critical', 'Major' or 'Minor'. Where the HTA is not presented with evidence that an establishment meets the requirements of an expected standard, it works on the premise that a lack of evidence indicates a shortfall.

The action an establishment will be required to make following the identification of a shortfall is based on the HTA's assessment of risk of harm and/or a breach of the Human Tissue Act 2004 (HT Act) or associated Directions.

1. Critical shortfall:

A shortfall which poses a significant risk to human safety and/or dignity or is a breach of the HT Act or associated Directions

or

A combination of several major shortfalls, none of which is critical on its own, but which together could constitute a critical shortfall and should be explained and reported as such.

A critical shortfall may result in one or more of the following:

- A notice of proposal being issued to revoke the licence
- Some or all of the licensable activity at the establishment ceasing with immediate effect until a corrective action plan is developed, agreed by the HTA and implemented.
- A notice of suspension of licensable activities
- Additional conditions being proposed
- Directions being issued requiring specific action to be taken straightaway

2. Major shortfall:

A non-critical shortfall that:

- poses a risk to human safety and/or dignity, or
- indicates a failure to carry out satisfactory procedures, or

- indicates a breach of the relevant Codes of Practice, the HT Act and other relevant professional and statutory guidelines, or
- has the potential to become a critical shortfall unless addressed

or

A combination of several minor shortfalls, none of which is major on its own, but which, together, could constitute a major shortfall and should be explained and reported as such.

In response to a major shortfall, an establishment is expected to implement corrective and preventative actions within 1-2 months of the issue of the final inspection report. Major shortfalls pose a higher level of risk and therefore a shorter deadline is given, compared to minor shortfalls, to ensure the level of risk is reduced in an appropriate timeframe.

3. Minor shortfall:

A shortfall which cannot be classified as either critical or major, but which indicates a departure from expected standards.

This category of shortfall requires the development of a corrective action plan, the results of which will usually be assessed by the HTA either by desk based review or at the time of the next inspection.

In response to a minor shortfall, an establishment is expected to implement corrective and preventative actions within 3-4 months of the issue of the final inspection report.

Follow up actions

A template corrective and preventative action plan will be sent as a separate Word document with both the draft and final inspection report. Establishments must complete this template and return it to the HTA within 14 days of the issue of the final report.

Based on the level of the shortfall, the HTA will consider the most suitable type of follow-up of the completion of the corrective and preventative action plan. This may include a combination of

- a follow-up inspection
- a request for information that shows completion of actions
- monitoring of the action plan completion
- follow up at next routine inspection.

After an assessment of the proposed action plan establishments will be notified of the follow-up approach the HTA will take.